Notes before Continuing

- Your currently saved settings will be reset to factory default on your Head Unit. You can take pictures of any settings you have changed, such as EQ sliders, so you can restore those settings after the update is complete.
- You will also require a blank USB device with a storage capacity of 32GB or less that is formatted in FAT32.
- We recommend updating to the latest version only if you are having issues or will be utilising one of the new features.
- This will be a two step update process which will require the update process to be done twice with two different groups of files.

You can check if your Aerpro headunit requires an update by navigating to the Version section on your headunit in the settings and comparing the date of the current firmware to that of the firmware on our Aerpro website.

o Settings	<u>r</u>			02:06 AM
Factory Reset				>
Version				>
Software Update				>
Open Source Licens	e			>
System Reboot				>
र्ट्रे General	ر) Audio	▶ Display	ح ريم Car Settings	Other
∽ Settings	₹ 0]			02:06 AM
Factory Reset				>
Version		.C200_V1.2		>
Software Update	SDK: 129.	40812_1820 (1.5.0.0.0.1.0		>
Open Source Licen		G_717_20240703 /935 V115-27	3_01.APQ.S	>
System Reboot				>
ر General	句) Audio	Display	Car Settings	Other

If the date on the Aerpro website is later than the date listed on your head unit, then an update is available.

Note, that there isn't any harm in updating the firmware anyway if you're unsure.

Toyota LC200 VX/Sahara 2016-2021 (<u>https://aerpro.com/AMUTO53</u>) Navigate to the Aerpro website (<u>https://aerpro.com</u>) and search for your head units model number based on the system version your head unit lists.


Need help searching for the right	t products? Check out our step by step video that g	juides you through the s
r?	Search	Find your headur
cific to a particular Vehicle by e and model of your vehicle.	AMUTO53 Search for a product, a vehicle that you are looking to have a product fit, or a product category.	Enter model Search for your h parts you'll need.

Scroll down the bottom and click the zip file to download the firmware update.

The files will be contained in a zip file. We can use Windows built in zip manager to open the zip file to view the files

Manuals & Firmware 🔹		
Manuals: 🛃 User Manual		
📓 Aerpro Head Unit Update Guide		
Firmware: 🎚 AMUTO53-Update-DATE		

Plug in the USB device, ensuring it is blank, 32GB or less and is formatted in FAT32. You can format the USB device by right clicking the USB device and selecting format. Here you can make sure it is set to FAT32. **PLEASE BE AWARE, ALL YOUR FILES WILL BE DELETED ON THE USB WHEN FORMATTING.**




ata (D:)	USB Drive (E:)		New Volum
15 GB free of 5.45 TB	14.8 GB free of 14.8 GB		3.36 TB free
	Format USB Drive (E:)	×	
	Capacity:		
	14.9 GB	\sim	
	File system		
	FAT32 (Default)	~	
	NTFS FAT32 (Default) exFAT		
	Restore device defaults Volume label		
	USB		
	Format options		
	Quick Format		
	Start	lose	

Once formatted, open up the downloaded zip file. Inside will be two folders. Step 1 & Step 2. Open up folder 1 and copy the contents onto the blank USB Device.

C200 16-21 v1.1 (202	240904) (S × +		<u>—</u> 38
$\leftarrow \rightarrow \uparrow$	C 🖵 > Downloads > L	C200 16-21 v1.1 (20240904) (STEP 1)	Search LC200 16
🕀 New - 🐰	0 6 0 0	↑↓ Sort ~ \equiv View ~ …	
> 🥌 OneDrive - Pers	Name	Date modified Type	Size
	ispbooot.bin	4/09/2024 9:44 AM BIN File	172,990 KB
□Desktop□Downloads□Documents□Pictures□Music□Videos	ISPBOOOT_UPDATE_P.BIN	28/08/2024 10-06 AM BIN Eila Edit in Notepad Add to Favourites 7-Zip 7-Zip Scan with Webroot Copy as path Copy as path Share Cut Cut Copy Create shortcut Delete Rename	1 KB
		Properties	

Once you have copied, navigate to your inserted USB drive and right click in the empty spot and click paste. There should be 2 files on the USB device. Safely remove the USB device and move back to your vehicle to install the first step firmware.




It is very important that the following steps are followed exactly.

To install the update, turn on the unit without the update USB connected. Then once fully booted, plug in the update USB into the USB port for the headunit (NOTE: USB port has to be grey USB port used for CarPlay/Android Auto, this would typically be connected to the factory USB)

The unit will then ask if you want to install an update. If a window doesn't appear then navigate to the settings menu, click other, then choose 'Software Update'. It should then come up with a message box asking if you want to update. If it does not, then the update may not be copied to the USB correctly and you should try the procedure again.

Once you have confirmed the update, the system may reset a couple of times and show a black screen in between. **DO NOT TURN OFF THE VEHICLE DURING THIS PROCEDURE.** Please be patient with the process. An update screen will appear. Continue waiting and you will get a screen that looks similar to below.



The home screen may appear during the update process, but **continue to wait until a progress bar appears with a black screen**. When the update is finished you will see the below message which means the update has been completed.




Please Remove the USB drive and restart the vehicle when this screen appears.

Once the head unit is finished restarting, we can move onto **STEP 2** of the update. Take the USB to the computer, plug it in and do another format, like the process above.

Local Disk (C:)	Data (D:)	USB (E:)	New Vo	olumę (
104 GB free of 930 GB	423 GB free of 5.45 TB	🗩 14.4 GE	Open	of
etwork locations (2)	425 05 166 01 5,45 16	- 14,4 GL	Open in new window	
and a contract of the contract			Pin to Quick access Turn on BitLocker	
			Give access to Open as Portable Device	
			7-Zip	
			CRC SHA	
			Pin to Start	
			 Permanently erase with Webroot Scan with Webroot 	
				_
			Format	
			Eject	
			Cut Comu	
			Сору	
			Create shortcut Rename	
			Properties	
ta (D:) 5 GB free of 5.45 TB	USB Drive (E:) 14.8 GB free of	14.8 GB	3.36 TE	3 free
	Format USB Drive (E:)		×	
	Capacity:			
	14.9 GB		~	
	File system			
	EAT32 (Default)		×	
	FAT32 (Default)		<u> </u>	
	NTFS			
	NTFS FAT32 (Default) exFAT			
	NTFS FAT32 (Default)			
	NTFS FAT32 (Default) exFAT Restore device defaults Volume label			
	NTFS FAT32 (Default) exFAT Restore device defaults Volume label USB			
	NTFS FAT32 (Default) exFAT Restore device defaults Volume label			
	NTFS FAT32 (Default) exFAT Restore device defaults Volume label USB Format options			
	NTFS FAT32 (Default) exFAT Restore device defaults Volume label USB			
	NTFS FAT32 (Default) exFAT Restore device defaults Volume label USB Format options			
	NTFS FAT32 (Default) exFAT Restore device defaults Volume label USB Format options			
	NTFS FAT32 (Default) exFAT Restore device defaults Volume label USB Format options			
	NTFS FAT32 (Default) exFAT Restore device defaults Volume label USB Format options			
	NTFS FAT32 (Default) exFAT Restore device defaults Volume label USB Format options	Clo		

Once formatted and confirmed to be empty, we should open up the STEP 2 folder and copy the single file onto the USB




Safely remove the USB device and move back to your vehicle to install the second step firmware.

It is very important that the following steps are followed exactly.

To install the update, turn on the unit without the update USB connected. Then once fully booted, plug in the update USB into the USB port for the headunit (NOTE: USB port has to be grey USB port used for CarPlay/Android Auto, this would typically be connected to the factory USB)

Nothing should appear when USB is inserted. This is OK. Navigate to the Settings, Other tab and then tap 'Factory Reset'. Confirm the factory reset device.


The unit will then reboot. Please do not touch anything while this process is happening. The head unit will automatically show the following screen with a progress bar like the image below. NOTE: It may reboot a couple of times during this process. Please wait until it finished and asks to remove the USB



If it does not, then the update may not be copied to the USB correctly and you should try the procedure again.

DO NOT TURN OFF THE VEHICLE DURING THIS PROCEDURE.

Please be patient with the process. Continue waiting and once the progress bar finishes you will get a screen that looks similar to below.



You will then be asked to **remove the USB BEFORE pressing the OK button** as the image above. Once the USB is taken out, you can continue by pressing the OK button on the screen. Pressing it once is sufficient, it will eventually restart. The update is now complete.

It is recommended to turn off the car, wait 30 seconds then turn it back on. Then you can check the date number to make sure it has updated successfully and you may change the settings to your taste.

Changelog

Latest (v1.1)

- Park assist slight design changes
- Trip info design changes
- Inclinometer design changes
- Adjust some text in settings
- Fixed Audio Slider Bug
- Improved Reliability with 360 camera
- Updated / changed various climate related designs and bugs
- New Features
 - Holding the Volume Down for one second on the steering wheel will quickly mute audio.
 - Holding down the 'moon' icon on the top right corner of the home screen will turn off the display and mute the audio