

to suit **TOYOTA LANDCRUISER**
200 SERIES SAHARA 2009-2015
AMUTO51 A, AMUTO51 B & AMUTO52

Factory Features Unable To Be Retained

- **Clock** - Clock relocated to aftermarket head unit home screen.
- **DVD Player & Associated Buttons/Dials** - Has no function and is replaced with the included pocket.
- **Independent Input for Rear Entertainment Screens (Fig.1)** - Independent video/audio inputs to play media on the rear entertainment screens cannot be retained. Video must be played from USB stick connected to the head unit for video function work (See Manual for more information).*
- **Headphones for Rear Entertainment (Fig.1)** - Audio output via headphones for rear entertainment including rear volume dials will not work.*
- **Auxiliary jack next to USB port** - Is not retained.*
- **Vehicle maintenance setting** - Previously accessed from factory screen.

Fig.1



**Only applicable to vehicles with these features.*