

## to suit **TOYOTA LANDCRUISER** 200 SERIES VX/SAHARA **2016-2021**

### Factory Features Unable To Be Retained

- **VFD Clock (Fig. 1)** - Clock relocated to aftermarket head unit home screen.
- **Climate Shortcut Button (Fig. 3)** - Factory button was not retained so a Climate button on the aftermarket head unit was added.
- **DVD Player & Associated Buttons/Dials (Fig. 2 & 4)** - Has no function and will not be able to play DVDs or adjust volume with the dials.
- **Audio Control from Head Unit to Rear Entertainment Screens** - Rear entertainment system can still be used standalone using the rear HDMI/AV ports (Refer to Manual FAQ for more information).
- **Auxiliary jack next to USB port** - Is not retained.
- **Audio source control from MFD** - Cannot change audio source of headunit using the MFD.
- **Vehicle maintenance setting** - Previously accessed from factory screen.



### **Attention: Vehicles without 360 camera (Reverse Camera Models).**

Your factory reverse camera is required to be upgraded using the supplied AHD 720p reverse camera. Please refer to the manual for more information.

This kit has not been configured to retain the original reverse camera as it is low resolution. Upgrading the camera is necessary to retain the reverse camera function.

In order to retain the factory amplifier, please ensure that you connect the **MOST** connector (Refer to Manual) and insert the white RCA plug labelled **(Stereo)** into the back of the head unit next to the blue connector. Please ensure that only the 59 pin plug is connected to the back of the original climate control system, if not, you may be presented with no audio. Please visit the manual for more information.



There is an adhesive label on the back of the headunit stating to refer to the manual for more information. For the Australian region, the 360 camera plug is white or black and not blue. If your vehicle has a 360 camera connector like **Fig. 1** you can plug the white connector straight into the back of the head unit. If your 360 camera vehicle connector, like **Fig. 2**, then you will need to use the included 360 camera adaptor to convert the 360 plug, and then connect it to the back of the head unit. Do not pair Blue with Blue. If the head unit is not displaying the 360 camera then ensure that the correct vehicle connector is plugged into the blue port of the head unit and that the **'R Camera In'** RCA from the main harness is also plugged into the **'R Camera'** of the AV Harness on the head unit **Fig. 3**.

